photos

MAR 6 1992

| T . 0.05.10   |  |                      | · · · · · · · · · · · · · · · · · · · |  | 411 0 100                    | <b>-</b>     |
|---|--|----------------------|---------------------------------------|--|------------------------------|--------------|
| •   | HA0/12   | 7111                 |                                       |  | EPIDEM                       | IOLOGIC      |
|   | 9111220001117  |                      |                                       |  |                              |              |
| 4. DATE OF YR ACCIDENT 9 1  | ACCIDENT INVESTIGATION   |                      |                                       | <del>                                     </del> | INVESTIGATION<br>REPORT      |              |
| * STMOPSIS OF ACCIDENT OR COMPLANT_ Complaint involved the unattended fire in a toaster oven, which wasn't in use for two (2) weeks prior to accident. Complainant stated she |  |                      |                                       |  |                              |              |
| was able to   | unplug t   | he burning           | toaster oven,                         | and exting                                       | guish flames                 | with a       |
| garden hose.  | . No pers  | onal injuri          | les but an exc                        | otic bird ,                                      | died from s                  | moke inhala- |
| tion. Proper  | ty damag   | e was estin          | mated, by vict                        | im to be le                                      | ess than \$500               | 0.00.        |
|   |  | ·                    |                                       |  | <del></del>                  |              |
| 7. LOCATION (Home, school, es   | r.   |                      | le cm                                 |  | 1                            |              |
| Home/indoors/kitchen 1 0 Oxford 9. ST.  |  |                      | V. SIAIE                              | MA   |                              |              |
| 10A. FIRST PRODUCT  |  | 11A.                 | TRADE/BRAND NAME, MOD                 | EL NUMBER. TOAS                                  | ster-Oven A97                | rll          |
| Toaster oven  | 0 2  | 1 6                  | Armstrong Rd.                         | Shelton, C                                       | Decker (U.S.<br>T. 06484-479 |              |
| None  | DB. SECOND PRODUCT  11B. TRADE/BRAND NAME, MODEL NUMBER,  MANUFACTURER & ADDRESS   |                      |                                       |  |                              |              |
| 12. AGE OF VICTIM   | 13. SEX (Use nu  | merical code)        | 14. DISPOSITION                       |  | 15. INJURY DIAGNOS           | · ·          |
| 9 9 9   | MALE<br>FEMALE<br>UNKNOWN  | ·1 9                 |                                       |  |                              | y 7 0        |
| 16. BODY PART   |  | 17. RESPONDENT(S) (A | Mother, Friend)                       | 18. TYPE INVES                                   | TIGATION 15                  | . TIME SPENT |
| _No _injury   | 9 9  | Victim/Com           | plainant 1                            | ON SITE<br>TELEPHONE<br>OTHER                    | 2 1                          | 120          |
| 20. ATTACHMENTS   |  | 21. CASE SOURCE      | CE                                    | 22. REVIEWED BY                                  | YR                           | MO DAY       |
| Multi   | 9  | Hot Li               | ne 0 7                                | 8 3 4  | 2 9 2                        | 0 3 0 2      |
| 23. PERMISSION TO DISCLOSE  | NAMES  |                      |                                       | •  |                              |              |
| (NON-NEISS CASES ONL  | ·  | CPSC MAY DIS         | CLOSE MY NAME XX                      | CPSC I   | MAY NOT DISCLOSE MY N        | AME          |
| 24. NARRATIVE (See Instructions on Other Side)  25. REGIONAL OFFICE DIRECTOR REVIEW DATE  |  |                      |                                       |  |                              |              |
| 3-2-92  |  |                      |                                       |  |                              |              |
| Investigation delayed because two sets of photos sent by victim, including insured letter were lost by U.S. Mail.   |  |                      |                                       |  |                              |              |
|   |  |                      |                                       |  | 4                            |              |
|   | Web los  | YELR MODIFIED        | ozinis made<br>ozits attached         |  |                              |              |
| The requested   |  |                      |                                       |  |                              |              |
|   | The state of the s |                      |                                       |  |                              |              |
|   | •  | (USE OTHER S         | IDE AND ADDITIONAL SHEETS             | S IF NECESSARY)                                  |                              |              |

#### 911122CCC1117

### PRE-ACCIDENT:

received

Investigation involved a consumer complaint via CPSC hot line, which involved a fire in counter top toaster oven. Complainant indicated she had received the toaster oven, new, as a wedding gift approximately three years ago. The complainant stated she used the toaster oven infrequently, maybe once every 10 days. The complainant stated there had been no history of any repairs with this appliance and there had been no electric problems in her apartment.

### <u>ACCIDENT</u>:

Complainant stated she works, part-time mornings, and had returned to the apartment. The complainant stated she was in bathroom area, with door closed, when she heard the smoke detector alarm. The complainant stated she came out and went toward front of the apartment and saw flames coming out of the toaster oven which was on a counter area in the kitchen. She went back into bathroom area for a towel, to protect her hands and was able to unplug the toaster oven from the wall receptable (Photo #3 & 4). However, there was still some burning area on the counter top and wall area in back of toaster oven. The complainant stated she had garden hose set-up which she activated and extinguished the fire.

#### POST-ACCIDENT:

Neighbor in next apartment had come to her assistance, when she heard the smoke detector go off and help her make sure all the fire was extinguished. The complainant had a number of exotic birds in the apartment and one of the birds, near the kitchen area, apparently died from smoke inhalation. The victim stated she had the maintenance man for the apartment complex, check the electric wall receptable to see if there was any problem with wiring. The victim stated the maintenance man found nothing wrong with apartment wiring, that the toaster oven was at fault.

Complainant stated she called "General Electric" hot line telephone and was advised that the fuse in the unit probably was bad and that a company representative would be in contact with her.

Complainant displayed letter from Black & Decker Consumer Assistance dated 10/18/91, signed by Gloria Fusco Claims Coordinator and returned cards to ship damaged oven for replacement.

### PRODUCT IDENTIFICATION - SEE PHOTOS #1-7

Toaster oven was a General Electric Model A9TII with a front panel (See Photo #2) showing "TOASTER-OVEN/toast'n broil" name. The main housing of oven is metal (13 in. wide x 7 in. high) with two side plastic handle attachments. The right front side of housing has temperature control top dial (BAKE/BROIL) with settings of "OFF" 200 300 400 500. BROIL", The bottom front dial setting has the setting for toaster heater portion "LIGHT-DARK TOP BRAND". In the space between these two temperature dials, is "push down" button to activate the toaster heating element of the oven.

### STANDARDS:

None applicable to this product.

### ATTACHMENT:

- 1. Photos #1-7 of toaster oven scenario
- 2. Photo Copy of Black & Decker Correspondence dated 10/18/91
- Photo Copy of Black & Decker Merchandise Return Label Coded G3404
- 4. Diagram of victim's apartment.

|  | 4  |   |  | •   |
|--|--|---|--|---|
| (9/1/5 TC-21 /   |  |   | FOR OFF  | CIAL USE ONLY                                       |
| E CONSUMER PRODUCT   | INCIDENT   | REPORT  |  | Jn-39   |
| Gail Fairbanks   | 2. PHONE   | NO. (HOME<br>87-0501  |  | WORK<br>55-5841                                     |
| 3. STREET ADDRESS 130-165 Sutton Rd.   | 4. CITY<br>Oxfor   | d   | STATE<br>MA  | ZIP CODE<br>01540                                   |
| 5. DESCRIBE INCIDENT OR HAZARD, INCLUDIN Home smoke alarm sounded, and consumer wwere coming out of the front of toaster time and had not been used for 2 weeks. behind toaster oven. Consumer unplugged window. Consumer patted out flames on wflames on toaster oven with a garden hos charred and melted on its outer surface  6. DATE 7.IF INJURY OR NEAR MISS OBTAT | vent to ki<br>oven, whi<br>Flames w<br>toaster<br>vall with<br>e. Toast<br>and insid     | tchen. 3' ch was not ere runnin oven and t a towel, a er oven wa e the oven | high fin use gup the hrew it nd extiss exten. Wall | lames at the wall out the nguished sively -cont     |
| OF 0 YR/N INCIDENTS AND DESCRIBE INJURY: 10/18/91 none   | N AGE/SEX  | RESPON<br>none  | TIM DIF<br>DENT, P<br>IONSHIP                      | ROVIDE NAME   |
| 9. DESCRIPTION OF PRODUCT toaster oven   | 10. BRAND NAME<br>General Electric   |   |  |   |
| 11. MFR/DISTRIBUTOR NAME, ADDR. & PHONE General Electric unknown   | 12. MODE<br>A9T11  | L, SERIAL   | NUMBERS  |   |
| Eridgeport, CT (zip unknown) unknown unknown unknown unknown   | 13. DEALER'S NAME, ADDRESS & PHONE Caldor's Auburn Mall Auburn, MA (zip unknown) unknown |   |  |   |
| 14. WAS THE PRODUCT DAMAGED, REPAIRED OR MODIFIED? YES x NO IF YES, BEFORE OR AFTER THE INCIDENT? after DESCRIBE:  | 15. PRODU<br>DATE PUR  | JCT PURCHAS<br>CHASED 1988  |  | EW x USED<br>AGE 3 yrs.                             |
| damaged: extensively charred and melted  | 16. DOES PRODUCT HAVE WARNING LABELS? IF SO, NOTE: none                                  |   |  |   |
| 17. HAVE YOU CONTACTED THE MANUFACTURER? YES NO X IF NOT, DO YOU PLAN TO CONTACT THEM? YES X NO OTHER?  18. IS THE AVAILABLE. IF NOT, IS   | ? YES >  | c NO  |  | 19. MAY WE USE YOUR NAME WITH THIS REPORT? YES x NO |
| FOR ADMINITION 20. DATE RECEIVED 21. RECEIVED BY   | Y (NAME &  |   |  | CUMENT NO.  |
| 10/18/91 JM/HI  23. FOLLOW-UP ACTION   |  |   |  | A0112A0 DDUCT CODE(S)                               |
| 9/1/1/1 CCC 1/17   | 13 NOV   | 1997  |  | DDGCT CODE(S)                                       |
| 25. DISTRIBUTION 26.   | ENDORSE<br>// (\)  | CR'S NAME &   | TITLE  |   |
| CPSC FORM 175 (9/89)   | \\\  | 1/1/  |  |   |
|  | •  | •   |  |   |



9111 22000 1117

October 18, 1991

EX#2

U.S. Household Products Group Consumer Assistance & Information Telephone: 1-800-231-9786

Gail Fairbanks 130-165 Sutton Rd Oxford MA 01540

Dear Ms Fairbanks:

Thank you for contacting us regarding your General Electric Toaster Oven.

We do value you as a customer and are sorry for any difficulties you may have encountered.

We would appreciate your returning the product to us for examination in our Engineering Laboratory. Please package it securely and follow the enclosed instructions for using the prepaid postage label we have furnished, to avoid any shipping expense to you.

When your product is received, arrangements will be made to ship a replacement, at no charge, to you. Allow two weeks for the delivery.

We appreciate your purchasing Black & Decker Household Products, and if we can be of assistance in the future, please let us know.

Sincerely,

Gloria Fusco

CLAIMS COORDINATOR

REF#:G3404

CH 3

| FROM:  | -       <br>-                 | NO POSTAGE NECESSARY IF MAILED IN THE UNITED STATES |
|--|-------------------------------|---|
| POSTAGE DUE UNIT:<br>CHARGE \$   |                               |   |
| MERCHANDISE<br>PERMIT #6174  | RETURN CARD SHELTON, CT 06484 |   |
| POSTAGE<br>U.S. POSTAL<br>SHELTON, C   |                               |   |
| C3404<br>FROM:   |                               | NO POSTAGE<br>NECESSARY<br>IF MAILED<br>IN THE      |
| MAILING POST OFFICE COMPUTE<br>POSTAGE DUE AT APPLICABLE RA'<br>ADD MERCHANDISE RETURN FEE<br>TOTAL POSTAGE DUE: |                               | UNITED STATES                                       |
| PERMIT #6174  BLACK & I ATT: ED KUS 6 ARMSTROM   | INSKI ( fleched               |   |

1/2 COOR. 91/1/22 @cc/117 LUMA Room Dirig of AREL

### 911122 CCC 1117

### U. S. CONSUMER PRODUCT SAFETY COMMISSION

| AUTHORIZATION FOR RELEASE OF NAME |
|-----------------------------------|
|                                   |

Thank you for assisting us in collecting information on a potential product safety problem. The Consumer Product Safety Commission depends on concerned people to share product safety information with us. We maintain a record of this information, and use it to assist us in identifying and resolving product safety problems.

We routinely forward this information to manufacturers and private labelers to inform them of the involvement of their product in an accident situation. We also give the information to others requesting information about specific products. Manufacturers need the individual's name so that they can obtain additional information on the product or accident situation.

Would you please indicate on the bottom of this page whether you will allow us to disclose your name. If you request that your name remain confidential, we will of course, honor that request. After you have indicated your preference, please sign your name and date the document on the lines provided.

| You are hereby authoriz with the information colle | ed to disclose my name and address |
|--|------------------------------------|
| My identity is to remain o                         | confidential.                      |
| / all all all all all all all all all al           | FEB. 20-1992                       |
| (Signature)  | (Date)                             |

Brshall Bosker

MOCIDENT INVESTIGATION REQUEST FORM

| equested By T Dones  ask Number 9/1/75CCC 1//7  ssigned to 1//  Date | HH<br>87-05 | Person(s) to Contact SAITE P |  | Document Number HIA 0//IAO  Date of Invident 10-18-9/ Category  Pollow-Op Requested Hazard Analysis  Type For its - To requested Telephone Call-  Hear wanters Contact 1 Jones  Assistant Message II prolife of the collection of th |
|--|-------------|------------------------------|--|--|
| 11/22/51   | 612.40      |                              |  | Category I.D. SECTO   Analysis  Section 15  On-Site  Car curs - Telephone of   |

behind toaster oven was scorched. Cabinets 2'-3' above toaster oven were scorched. Parakeet in kitchen died of smoke inhalation.

Later that day, building maintenance man (name unknown) checked wiring in apartment to see if faulty wiring had caused fire. Person said there was nothing wrong with wiring, and toaster oven was at fault.


Toaster oven was clean at time of incident.

Toaster oven has a plastic and metal outer body and a glass door.

Toaster oven is UL listed 473A.


Consumer found CPSC hotline number in phonebook.

## 911122 ccc 1117 Ex#1




FRONT OF TOASTER OVEN - DOOR OPEN - SHOWING SCOREHING

# 911122 ccc 1117 Ex#1



FRONT OF TOASTER DVEN - DOOR OPEN - SHOWING SCOREHING



FRONT OF TOASTER. DUEN-DOOR OPEN SHOWING SCORCHING.






KITCHEN COUNTER WALL
RECEPTACLE
WHERE
TOASTER OVEN
WAS PLUGGED
IN - ON DAY
OF FIRE
WHILL & COUNTER
HAVE BEEN
LEPAIRED
NO AMPTOR REPORTERYIN USE.




G) TWO WIRE NOW/POLARIZED PLVG .

WIRE LABBLESS
"HAN HEATER.
10/24 FIW.
16/2
FSM CSA"




KITCHEN COUNTER.
WALL
RECEPTACLE
WHERE
TRASTER OVEN.
WAS PLUGGED
IN - ON DAY OF
FURE
WALL + COUNTER
HAVE BEEN
REPRIREDNO ADAPTOR
REPORTEDLY IN
USE




4

TWO
WIFE
NON
POLARIZED
PUBLIC
WIFE
WARE
WHEATER
WEATER
WOLF FW
IND
ESA
"

3



BOTTOM OF TOASTER OVEN-SHOWING ELECTRIC CONNECTOR BLUCK-AND HEATER ELEMENTS




BOTTOM OF TOASTER OVEN - SHOWING ELECTRIC CONNECTOR BLOCK AND HEATER ELEMENTS.

# 9/11/22 ecc 11/7



BOTTOM PLATE - ENCRAVER.
"DISEONNECT TOASTER BEFORE CLEANING"

### 911122 CCC 1117 Ex#1



BOTTOM PLATE -EXIGRAVED.
"DISCONNECT TOASTER BEFORE CLEANING"